

# 1

25X1  
25X1  
25X1

1. IMAGE QUALITY IS GOOD FOR THIS SYSTEM THROUGHOUT FIRST 423 FRS. SHUTTER MALFUNCTIONED AND REMAINED CLOSED AFTER FR 423 RESULTING IN 70 UNEXPOSED FRS WHICH WERE NOT REPRODUCED. PI SUITABILITY IS CONSIDERED TO BE FAIR. CLOUDS OBSCURE APPROX 10 PCT OF ENTIRE MSN.

A. MSN NO: M-280A  
B. DATE: 18 OCT 70  
C. CAM NO: B-229, A/C TAIL NO: 051  
D. MODE: III/IV  
E. T/O: 0650Z, C/ON: 1030Z  
F. FILM TYPE: 3400  
G. SHUTTER SPEED: 1/250  
H. FILTER: W-12

3. ORIG NEG.  
A. EXPOSURE: GOOD

25X1

C. PHYSICAL DEGRADATION: NONE.

D. IMAGED DEGRADATION: MINOR PLUS DENSITY FOG PATTERN

TWO INCHES FROM DATA BLOCK ON BOTH 9L AND 9R FRs.

E. AUX DATA: POSITION INDICATORS MISSING INTERMITTENT  
OTHER DATA IMAGED PROPERLY.

F. LAST TITLED FR: 423 LEFT, 422 RIGHT

4. POSITIVES: PRINTING AND PROCESSING GOOD. POSITIVES  
SUITABLE FOR INTERPRETATION.

S E C R E T

--END OF MESSAGE-- GP-1

NTLY. DISTRIBUTION		
CY	OFFICE	PI
<i>1</i>	FILE	
<i>2</i>	CABLE SEC.	
	INFO/AD	
<i>3</i>	RECDR.	
<i>4</i>	REC	<i>APD</i>
	INFO/AD	
	INFO	
	INFO/RS	
	INFO	25X
<i>5</i>	INFO/AD	
	SUBIN	
	WEST	
	EAST	
	NBS	
<i>6</i>	INFO/AD	
	INFO	
	INFO-SEC	
	LEAD	
	[Redacted Box]	25X

ADVANCE CY  
SANITIZED  
WITH TEXT

**SECRET**